



part plan of roof _ scale 1:200

12



elevation 12_ scale 1:100

Legend: Deterioration Mapping (Based on ICOMOS - ISCS Illustrated Glossary 2008)

Crack & Deformation	Biological Colonisation	Detachment	Disintegration including Powdering	Features Induced By Material Loss	Discoloration & Deposit	Others
Crack	Biological Colonisation	Blistering	Disintegration including Powdering	Alveolisation	Crust	Metal Inserts
Deformation	Higher Plants	Delamination including Exfoliation	Delamination including Exfoliation	Erosion including Differential Erosion	Efflorescence	Accretions
				Missing Part	Graffiti	Back Weathering
				Mechanical Damage	Encrustation	Cement Rendering
					Patina	
					Rust Staining	



NOTES:

REVISION MARK

Atelier Periti
 Conservation, Architecture and Civil Engineering
 Chantal, 5 Zammit Hammet Street Balzan
 Tel: 7942 9875

THIS DRAWING REMAINS THE PROPERTY OF ATELIER PERITI AND MUST NOT BE USED OR COPIED WITHOUT WRITTEN PERMISSION.

TITLE
 EXISTING DETERIORATION OF THE SOUTH SIDE OF THE SOUTH BELFRY (ELEVATION 12)

JOB
 PROPOSED RESTORATION OF THE MAIN FACADE OF THE FLORIANA PARISH CHURCH

PROJECT ARCH	M.A.	LOC. NO.	-
CHECKED	-	CAD REFERENCE	-
DRAWN BY	-		
SCALE	1:100	DRAWING NO.	315/20/20
DATE	04/08/2021		
JOB NO	315/20		