




proposed scuptural reliefs in the frontispiece_ scale 1:100



main facade (elevation 01)_ scale 1:100

Legend: Deterioration Mapping (Based on ICOMOS - ISCS Illustrated Glossary 2008)

Crack & Deformation		Detachment		Features Induced By Material Loss		Discoloration & Deposit		Others	
	Crack		Biological Colonisation		Blistering		Alveolisation		Metal Inserts
	Deformation		Higher Plants		Disintegration including Powdering		Deposit		Accretions
					Delamination including Exfoliation		Encrustation		Back Weathering
					Mechanical Damage		Graffiti		Cement Rendering
					Erosion including Differential Erosion		Efflorescence		Rust Staining
					Missing Part		Patina		



NOTES:			
REVISION MARK			
Atelier Periti			
Conservation, Architecture and Civil Engineering			
Chantal, 5 Zammit Hammet Street Balzan			
Tel: 7942 9875			
THIS DRAWING REMAINS THE PROPERTY OF ATELIER PERITI AND MUST NOT BE USED OR COPIED WITHOUT WRITTEN PERMISSION.			
TITLE			
PROPOSED SCULPTURE ON THE MAIN FACADE (ELEVATION 01)			
JOB			
PROPOSED RESTORATION OF THE MAIN FACADE OF THE FLORIANA PARISH CHURCH			
PROJECT ARCH	M.A.	LOC. NO	--
CHECKED	--	CAD REFERENCE	--
DRAWN BY	--		
SCALE	1:100	DRAWING NO.	
DATE	11/08/2021		305/20/42
JOB NO	315/20		