


























REVISION MARK	-								
<p align="center">Atelier Periti <i>Conservation, Architecture and Civil Engineering</i> Chantal, 5 Zammitt Hammet Street Balzan Tel: 7942 9875</p> <p align="center">THIS DRAWING REMAINS THE PROPERTY OF WRITER PERITI AND MUST NOT BE USED OR COPIED WITHOUT WRITTEN PERMISSION.</p>									
<p>TITLE</p> <p align="center">EXISTING DETERIORATION OF THE PORCH SIDE WALLS (ELEVATIONS 02 AND 03)</p>									
<p>JOB</p> <p align="center">PROPOSED RESTORATION OF THE MAIN FACADE OF THE FLORIANA PARISH CHURCH</p>									
PROJECT ARCH		M.A.	LOC. NO.	-					
CHECKED			CAD REFERENCE						
DRAWN BY									
SCALE		1:50	DRAWING NO.						
DATE		04/08/2018	305/20/13						
JOB NO		315/20							

Legend: Deterioration Mapping (Based on ICOMOS - ISCS Illustrated Glossary 2008)

Crack & Deformation		Detachment		Features Induced By Material Loss		Discoloration & Deposit				Others													
	Crack		Biological Colonisation		Blistering		Disintegration including Powdering		Aveolisation		Missing Part		Crust		Efflorescence		Graffiti		Rust Staining		Metal Inserts		Back Weathering
	Deformation		Higher Plants		Delamination including Exfoliation		Detachment		Erosion including Differential Erosion		Mechanical Damage		Deposit		Encrustation		Patina				Accretions		Cement Rendering

